

Drilling of steels and stainless steels. Cutting comfort and speed, service life.




- Especially for high-strength steels, stainless steels and cast irons
- Maximum long life
- Incredibly fast milling
- Comfort and precision
- Made in France
- Weldon shank
- High-speed steel
- TiAlN coating



## Machine



## Application



## Features



## Properties and benefits

- + Weldon shank: cylindrical shank with 3/4" flats. ⚙️ Particularly suited for the attachment of tools to drills with a magnetic base.
- + High-speed steel: HSS substrate ⚙️ For general use in steels and cast irons up to 950 N/mm²
- + TiAlN coating: TiAlN base, thickness 2/4µm, hardness 3000HV, coefficient of friction 0.4, heat resistance 900°C. ⚙️ Thermal shield. Allows you to increase service life, cutting speed, and progress. Reduces the axial load. Versatile uses.

| Code        | EAN           | Ø  | Internal Ø | d2   | L  | I  | Qty | PCB |
|-------------|---------------|----|------------|------|----|----|-----|-----|
| 10370111200 | 3221910825331 | 12 | 6          | 3/4" | 80 | 50 | 1   | 1   |
| 10370111300 | 3221910825348 | 13 | 6          | 3/4" | 80 | 50 | 1   | 1   |
| 10370111400 | 3221910825355 | 14 | 6          | 3/4" | 80 | 50 | 1   | 1   |
| 10370111500 | 3221910825362 | 15 | 6          | 3/4" | 80 | 50 | 1   | 1   |
| 10370111600 | 3221910825379 | 16 | 7          | 3/4" | 80 | 50 | 1   | 1   |
| 10370111700 | 3221910825386 | 17 | 8          | 3/4" | 80 | 50 | 1   | 1   |
| 10370111800 | 3221910825393 | 18 | 9          | 3/4" | 80 | 50 | 1   | 1   |
| 10370111900 | 3221910825409 | 19 | 10         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112000 | 3221910825416 | 20 | 11         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112100 | 3221910825423 | 21 | 12         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112200 | 3221910825430 | 22 | 14         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112300 | 3221910825447 | 23 | 14         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112400 | 3221910825454 | 24 | 15         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112500 | 3221910825461 | 25 | 16         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112600 | 3221910825478 | 26 | 17         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112700 | 3221910825485 | 27 | 18         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112800 | 3221910825492 | 28 | 19         | 3/4" | 80 | 50 | 1   | 1   |
| 10370112900 | 3221910825508 | 29 | 20         | 3/4" | 80 | 50 | 1   | 1   |

Drilling of steels and stainless steels. Cutting comfort and speed, service life.

|             |               |    |    |      |    |    |   |   |
|-------------|---------------|----|----|------|----|----|---|---|
| 10370113000 | 3221910825515 | 30 | 21 | 3/4" | 80 | 50 | 1 | 1 |
| 10370113100 | 3221910825522 | 31 | 22 | 3/4" | 80 | 50 | 1 | 1 |
| 10370113200 | 3221910825539 | 32 | 23 | 3/4" | 80 | 50 | 1 | 1 |
| 10370113300 | 3221910825546 | 33 | 24 | 3/4" | 80 | 50 | 1 | 1 |
| 10370113400 | 3221910825553 | 34 | 25 | 3/4" | 80 | 50 | 1 | 1 |
| 10370113500 | 3221910825560 | 35 | 26 | 3/4" | 80 | 50 | 1 | 1 |
| 10370113600 | 3221910825577 | 36 | 27 | 3/4" | 80 | 50 | 1 | 1 |
| 10370113700 | 3221910825584 | 37 | 28 | 3/4" | 80 | 50 | 1 | 1 |
| 10370113800 | 3221910825591 | 38 | 29 | 3/4" | 80 | 50 | 1 | 1 |
| 10370113900 | 3221910825607 | 39 | 30 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114000 | 3221910825614 | 40 | 31 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114100 | 3221910825621 | 41 | 32 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114200 | 3221910825638 | 42 | 33 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114300 | 3221910825645 | 43 | 34 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114400 | 3221910825652 | 44 | 35 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114500 | 3221910825669 | 45 | 36 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114600 | 3221910825676 | 46 | 37 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114700 | 3221910825683 | 47 | 38 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114800 | 3221910825690 | 48 | 39 | 3/4" | 80 | 50 | 1 | 1 |
| 10370114900 | 3221910825706 | 49 | 40 | 3/4" | 80 | 50 | 1 | 1 |
| 10370115000 | 3221910825713 | 50 | 41 | 3/4" | 80 | 50 | 1 | 1 |